

Danielle Greene

From: Marinez, Adriana <AMarinez@tep.com>
Sent: Tuesday, January 25, 2022 9:04 AM
To: COB_mail
Cc: Carmine DeBonis; Eddy, Steven
Subject: TEP W. Speedway Substation: Stabilization Photos
Attachments: West Speedway 46kV Distribution Line Emergency Repair Stabilization.pdf

CAUTION: This message and sender come from outside Pima County. If you did not expect this message, proceed with caution. Verify the sender's identity before performing any action, such as clicking on a link or opening an attachment.

Honorable Members of the Board of Supervisors,

The attached photos are in reference to your Dec. 7 discussion (agenda addendum #6) involving TEP's emergency work near its W. Speedway Substation.

After completing emergency work at the substation in July to quickly restore power to customers, TEP has worked with Pima County Public Works to stabilize the site, although not required per state statutes. Before and after photos are attached for your reference.

Please let me know if you have any questions or concerns related to this or any other TEP-related matter.

Kind regards,

Adriana Mariñez
Senior Local Affairs Representative
Tucson Electric Power & UniSource Energy Services
520-528-1512 (c)

CLERK'S NOTE:
COPY TO SUPERVISORS
COUNTY ADMINISTRATOR

DATE 1.25.22 DB
CC: Public Works Carmine DeBonis

JAN 25 22 09:03 PC CLK OF BD. DG

West Speedway 46kV Distribution Line Emergency Repair Stabilization

Site Location:

3651 West Speedway Blvd/Gates Pass Road

Photographer:

Brian Pugh

Date:

Oct/Dec 2021

Photo No. 1**Photo Description:**

Multi-armed saguaro that was blown down with the three poles including the communication lines and the electrical conductor.



Photo No. 2

Photo Description:

After stabilization.
Saguaro was removed
from the access road as
requested by the County
ROW inspector.



Photo No. 3

Photo Description:
Central access road
after emergency repair
looking east.



Photo No. 4

Photo Description:
Central access road
after stabilization
looking east.



Photo No. 5

Photo Description:
Central access road
after emergency repair
looking west.




Photo No. 6	
Photo Description: Central access road after stabilization looking west.	

Photo No. 7

Photo Description:

East access road after
emergency repair
looking west.



Photo No. 8

Photo Description:

East access road after stabilization looking west.



Photo No. 9

Photo Description:

East access road after
access control looking
east.

